



Nothing else measures up!

Follow us!



Prospect House
George Cayley Drive
Clifton Moor
York
England
YO30 4XE

Tel: +44 (0) 1904 692723
Fax: +44 (0) 1904 690385

E-Mail: sales@yorksurvey.co.uk



Digital Probe Thermometer



Operating Instructions

Digital Probe Thermometer

Specification:

Range:	-50 ~ +150°C
Resolution:	0.1°C or 0.1°F
Accuracy:	±1°C
Battery:	1.5V AAA
Sensor Type:	Thermistor
Display:	12.7mm LCD
Dimensions:	20 x 65 x 97mm
Weight:	100g

Instrument Operation:

The instrument is switched on by pressing the on/off button located on the front of the instrument. Within one second the thermometer is ready to work. Apply the tip of the probe to the substance, medium or surface to be measured. The instrument reading may take a few seconds to stabilise, depending on the nature of the measurement.

MAX/MIN Memory Function:

Press MAX/MIN button to display the maximum reading and a MAX symbol will flash in the display. Press the MAX/MIN button again to display the minimum reading and a MIN symbol will flash in the display. Press MAX/MIN button again to return to normal readings. To clear the MAX/MIN temperature memory, press the MAX/MIN and ON/OFF buttons simultaneously.

Battery Replacement:

Replace the battery using a 1.5V AAA or equivalent. The battery is located under the sliding battery cover at the rear of the instrument.

EMC/RFI:

Instrument readings may be affected if the unit is operated within a radio frequency electromagnetic field strength of approximately 3 volts per metre.

Guarantee:

This instrument is guaranteed for a period of one year from the date of purchase against mechanical and electrical manufacturing defects. There are no user serviceable parts inside the instrument. Any attempted repair by unauthorised persons voids warranty. Return to York Survey Supply Centre for service/repair.