



### Nothing else measures up!

Follow us! York Survey Supply Centre @York\_Survey @York\_Survey

Prospect House George Cayley Drive Clifton Moor York England YO30 4XE


Tel: +44 (0) 1904 692723 Fax: +44 (0) 1904 690385

E-Mail: sales@yorksurvey.co.uk





K-Type Folding Probe Thermometer



# **Operating Instructions**

## **K-Type Folding Probe Thermometer**

#### **Specifications**

Temperature $-199^{\circ}C$  to  $300^{\circ}C$  or  $-328^{\circ}F$  to  $572^{\circ}F$  for probes supplied<br/> $-199^{\circ}C$  to  $1300^{\circ}C$  or  $-328^{\circ}F$  to  $2000^{\circ}F$  with suitable probesResolution $0.1^{\circ}C$  or  $0.1^{\circ}F$ Accuracy $\pm 1^{\circ}C$  (-49^{\circ}C to 740^{\circ}C) or  $\pm 1.8^{\circ}F$  (-56.2°F to 1364°F)<br/>Otherwise  $\pm 2^{\circ}C$  or  $\pm 4^{\circ}F$ Power2x 3V CR2032 Button Cell

#### Features

On/Off Data Hold/Test Min/Max memory since power on °C/°F Selection Folding probe connector

#### Operation

Power "on" by pressing the on/off button. Power "off" by pressing the on/off button. Plug into the connector the relevant probe for your application. Press °F/°C button to select temperature format. Data Hold Test. Press H/T button once to hold the displayed value on the display. Press H/T again to return to the testing mode. Min/Max memory. Press min/max button once to display the maximum recorded values since power on. Press the same button again to display.

#### **Additional Probes**

A wide selection of K-Type probes is available form York Survey Supply Centre to suit many different applications.

#### Warranty

The product is warranted for 12 months from date of purchase. Should you need to return the product to us, please include a copy of the invoice as proof of purchase.

©York Survey Supply Centre 2019