



Trumeter Measurimeter Revolution

Code: 49205

Operating Instructions



Press button and hold (3 seconds) to clear displayed measurement.



Press button to freeze the displayed measurement. Freeze symbol ()

ON



Press button to turn on the display. Activates backlight for 5 seconds.



Press button to toggle between total and trip display.



Press button to select units of measure (feet, yards or metres), before or after taking measurement.

Prospect House, George Cayley Drive, Clifton Moor, York, England, YO30 4XE
Tel: +44 (0) 1904 692723 • Fax: +44 (0) 1904 690385
Website: www.YorkSurvey.co.uk • E-Mail: sales@yorksurvey.co.uk



Trumeter Measurimeter Revolution

Code: 49205

Operating Instructions



Press button and hold (3 seconds) to clear displayed measurement.



Press button to freeze the displayed measurement. Freeze symbol ()


ON



Press button to turn on the display. Activates backlight for 5 seconds.



Press button to toggle between total and trip display.



Press button to select units of measure (feet, yards or metres), before or after taking measurement.

Prospect House, George Cayley Drive, Clifton Moor, York, England, YO30 4XE
Tel: +44 (0) 1904 692723 • Fax: +44 (0) 1904 690385
Website: www.YorkSurvey.co.uk • E-Mail: sales@yorksurvey.co.uk