



Nothing else measures up!

Follow us!



Prospect House
George Cayley Drive
Clifton Moor
York
England
YO30 4XE

Tel: +44 (0) 1904 692723
Fax: +44 (0) 1904 690385

E-Mail: sales@yorksurvey.co.uk



Pen-Type Thermo-Hygrometer



Operating Instructions

Pen-Type Thermo-Hygrometer

Specifications

Temperature: 0°C to 50°C or 0°F to 122°F

Resolution: 0.1°C or 0.1°F

Accuracy: ±1°C or ±1.8°F

Humidity: 20%RH to 100%RH

Resolution: 0.1%RH

Accuracy: ±3%RH from 30% to 70%RH, (otherwise ±5%RH)

Power: 1x 3V CR2032 Button Cell

Features

On/Off

Min Max memory since power on

°C/°F selection

Soft touch rubberised plastic housing

Sintered rotating sensor protector

Operation

Power "on" by pressing the on/off button

Power "off" by pressing the on/off button

Rotate sintered sensor protector to expose the sensors

Press °C/°F button to select temperature format

Min Max memory. Press min/max button once to display the maximum recorded values

since power on. Press the same button again to display the minimum recorded value

since power on. Press the same button a third time to return to current value.

Warranty

The product is warranted for 12 months from date of purchase. Should you need to return the product to us please include a copy of the invoice as proof of purchase.

